



BRAKE REPAIR KITS


DANA 12-1/4" "FT" WITH OPEN ROLLER END

	LB-2		REPLACES	
	2 - B151 Retainer			
	2 - B216 Anchor Pin			
	1 - B307 Spring			
	2 - B362 Bushing			
	4 - B380 Lock			
	4 - B392 Washer			
	2 - B423 Pin			
	2 - B911 Roller			
	"Fast Rise" Cams July 1989-1994			
	LB-9			
	2 - B586 Roller (Replaces B911)		FMS LINING NUMBER(S)	
	For New Head Design Camshafts Since July 1994		4536 (5-1/2") 4692 (7-1/2")	

DANA 12-1/4" "FC-III" TRAILER AXLE

	LB-10		REPLACES	
	2 - B120 Anchor Pin			
	2 - B151 Retainer			
	2 - B220 Spring			
	1 - B307 Spring			
	2 - B423 Pin			
	2 - B586 Roller			
	2 - B888 Bushing			
	LB-10R			
	2 - B434S Spring (Replaces B220)		FMS LINING NUMBER(S)	
			4661 (5") 4536 (5-1/2") 4692 (7-1/2")	

RETRO-FITS SPIDERS WITH 1" ANCHOR PIN TO "FC-III" SHOE

	LB-11		REPLACES	
	2 - B151 Retainer			
	2 - B216 Anchor Pin			
	2 - B220 Spring			
	1 - B307 Spring			
	2 - B362 Bushing			
	4 - B380 Lock			
	4 - B392 Washer			
	2 - B423 Pin			
	2 - B586 Roller			
	LB-11R			
	2 - B434S Spring (Replaces B220)		FMS LINING NUMBER(S)	
			4661 (5") 4536 (5-1/2") 4692 (7-1/2")	

Copyright 2005 Sirco Industries, Inc.