



BRAKE REPAIR KITS

| RETRO-FITS SPIDERS WITH 1" ANCHOR PIN TO "FC-III" SHOE | | | | | | |
|--|---|---|-------|--------|--|----------------------------|
|  | LB-12 | REPLACES | | | | |
| | 2 - B151 Retainer 2 - B216 Anchor Pin 2 - B220 Spring 1 - B307 Spring 2 - B362 Bushing 4 - B380 Lock 4 - B392 Washer 2 - B423 Pin 2 - B911 Roller | <table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th style="width: 50%; text-align: center;">LB-12</th> <th style="width: 50%; text-align: center;">LB-12R</th> </tr> </thead> <tbody> <tr> <td style="font-size: x-small;"> Batco BWP Euclid Leland Meritor Midland Spicer </td> <td style="font-size: x-small; text-align: center;"> 08-105010 08-105010 </td> </tr> </tbody> </table> | LB-12 | LB-12R | Batco BWP Euclid Leland Meritor Midland Spicer | 08-105010 08-105010 |
| | LB-12 | LB-12R | | | | |
| Batco BWP Euclid Leland Meritor Midland Spicer | 08-105010 08-105010 | | | | | |
| LB-12R | FMS LINING NUMBER(S) | | | | | |
| 2 - B434S Spring (Replaces B220) | 4661 (5") 4536 (5-1/2") 4692 (7-1/2") | | | | | |

| SPECIAL KIT CONTAINS 1" AND 1-1/4" ANCHOR PINS | | | | |
|---|---|---|--|----------|
|  | LB-10S | REPLACES | | |
| | 2 - B120 Anchor Pin 2 - B151 Retainer 2 - B216 Anchor Pin 1 - B307 Spring 4 - B380 Lock 4 - B392 Washer 2 - B423 Pin 2 - B434S Spring 2 - B586 Roller 2 - B888 Bushing | <table border="1" style="width: 100%; border-collapse: collapse;"> <tbody> <tr> <td style="font-size: x-small;"> Batco BWP Euclid Leland Meritor Midland Spicer </td> <td style="font-size: x-small; text-align: center;"> HK49-150 </td> </tr> </tbody> </table> | Batco BWP Euclid Leland Meritor Midland Spicer | HK49-150 |
| | Batco BWP Euclid Leland Meritor Midland Spicer | HK49-150 | | |
| FMS LINING NUMBER(S) | 4661 (5") 4536 (5-1/2") 4692 (7-1/2") | | | |

