







CAMSHAFT SUPPORT BRACKETS

PART NO.	NOTES	REPLACES	
 B8734	For Fruehauf	Batco BWP Euclid Fruehauf Leland Meritor Spicer	03-251 M-1048 AXA0430-1 L-899 30-1363
 B8728	For Fruehauf 16-1/2" Axle Bracket	Batco BWP Euclid Fruehauf Leland Meritor Spicer	03-273 M-2595 E-4586 ACF4024-1 L-2712 R630006 30-1392
 B8727	For Fruehauf 12-1/4" And 16-1/2" Brakes	Batco BWP Euclid Fruehauf Leland Meritor Spicer	03-272 E-4587 ACF4021-1 ACF4022-1 L-2711 R630007
 B8727A	For Fruehauf 12-1/4" And 16-1/2" Brakes B8727 Assembly And B8624 Bushing	Batco BWP Euclid Leland Meritor Spicer	03-279 M-2594 30-1390
 B8725	For Fruehauf 16-1/2" Brakes Includes B8728 Bracket And B8727 Assembly	Batco BWP Euclid Leland Meritor Spicer	03-270 L-2707
 B8725A	Same As Above Except Includes B8624 Bushing	Batco BWP Euclid Fruehauf Leland Meritor Spicer	03-278 E-4594 ACF4024-900 L-3040 R630009