







CAMSHAFT BUSHINGS

PART NO.	NOTES	REPLACES
 B8696 or B8696HD	For Meritor Trailer Axles	Batco 03-209 BWP M-1521 Euclid E-1318A/HD Leland L-2854 Meritor A3105V282 Spicer 30-1358
 B8150L	Retro-Fit Camshaft Support Bushing Assembly Greasable	Batco 03-2082 BWP Euclid E-11445 Leland L-3485 Meritor Spicer 30-1341L M10WH150L
 B8150R	Retro-Fit Camshaft Support Bushing Assembly Greasable	Batco 03-2081 BWP Euclid E-11446 Leland L-3484 Meritor Spicer 30-1341R M10WH150R
 B8760	Outside Diameter 1-5/8" Inside Diameter 1-1/4" Length 1-3/16" Nylon For Meritor 15" "Q" Front Brakes	Batco 02-244 BWP M-3237 Euclid E-3877 Leland L-2939 Meritor 1225R1136 Spicer 28-1265
 B8600A	Outside Diameter 1-7/8" Inside Diameter 1-1/2" Length 1-3/16" Greaseless Nylatron For Meritor Drive Axles	Batco 02-210 BWP Euclid E-5512 Leland L-3029 Meritor 1225L1208 Spicer
 B8600	Outside Diameter 1-7/8" Inside Diameter 1-1/2" Length 1-1/4" Nylon	Batco 02-202 BWP M-571 Euclid E-536 Leland L-166 Meritor Spicer 28-1233

Copyright 2005 Sirco Industries, Inc.