




BRAKE REPAIR KITS

EATON 12-1/4" SINGLE ANCHOR PIN BRAKE																		
	LB-4	REPLACES																
	1 - B424 Anchor Pin 2 - B425 Roller 1 - B426 Spring 2 - B427 Spring 1 - B428 Washer 1 - B429 Nut 1 - B8604 Lock 2 - B8607 Washer	<table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th colspan="2" style="text-align: center; background-color: black; color: white;">LB-4</th> <th style="text-align: center; background-color: black; color: white;">LB-4A</th> </tr> </thead> <tbody> <tr> <td style="font-size: x-small;">Batco</td> <td style="font-size: x-small;">08-107600</td> <td rowspan="6" style="font-size: x-small; vertical-align: middle;">08-107602 K-106</td> </tr> <tr> <td style="font-size: x-small;">BWP</td> <td style="font-size: x-small;">M-K46</td> </tr> <tr> <td style="font-size: x-small;">Euclid</td> <td style="font-size: x-small;">E-2126</td> </tr> <tr> <td style="font-size: x-small;">Leland</td> <td style="font-size: x-small;">R507000</td> </tr> <tr> <td style="font-size: x-small;">Meritor</td> <td style="font-size: x-small;">CQ67388</td> </tr> <tr> <td style="font-size: x-small;">Spicer</td> <td style="font-size: x-small;">HK40</td> </tr> </tbody> </table>	LB-4		LB-4A	Batco	08-107600	08-107602 K-106	BWP	M-K46	Euclid	E-2126	Leland	R507000	Meritor	CQ67388	Spicer	HK40
	LB-4		LB-4A															
Batco	08-107600	08-107602 K-106																
BWP	M-K46																	
Euclid	E-2126																	
Leland	R507000																	
Meritor	CQ67388																	
Spicer	HK40																	
LB-4A	FMS LINING NUMBER(S) 4591 (7-1/2")																	
Above Less: 1 - B424 Anchor Pin 1 - B428 Washer 1 - B429 Nut																		

FRUEHAUF "PROPAR" 12-1/4" BRAKE																
	LB-5	REPLACES														
	2 - B054 Roller 2 - B423 Pin 2 - B495 Bushing 2 - B832 Anchor Pin 2 - B868 Retainer 1 - B869 Spring 2 - B932 Lock	<table border="1" style="width: 100%; border-collapse: collapse;"> <tbody> <tr> <td style="font-size: x-small;">Batco</td> <td style="font-size: x-small;">08-107700</td> </tr> <tr> <td style="font-size: x-small;">BWP</td> <td style="font-size: x-small;">M-K47</td> </tr> <tr> <td style="font-size: x-small;">Euclid</td> <td style="font-size: x-small;">E-2286</td> </tr> <tr> <td style="font-size: x-small;">Leland</td> <td style="font-size: x-small;">K-105</td> </tr> <tr> <td style="font-size: x-small;">Meritor</td> <td style="font-size: x-small;">R507005</td> </tr> <tr> <td style="font-size: x-small;">Midland</td> <td style="font-size: x-small;">CQ67394</td> </tr> <tr> <td style="font-size: x-small;">Spicer</td> <td style="font-size: x-small;">HK41</td> </tr> </tbody> </table>	Batco	08-107700	BWP	M-K47	Euclid	E-2286	Leland	K-105	Meritor	R507005	Midland	CQ67394	Spicer	HK41
	Batco	08-107700														
BWP	M-K47															
Euclid	E-2286															
Leland	K-105															
Meritor	R507005															
Midland	CQ67394															
Spicer	HK41															
	FMS LINING NUMBER(S) 4649 (8")															

MERITOR 12-1/4" "Q" BRAKE																
	LB-3	REPLACES														
	2 - B120 Anchor Pin 2 - B134 Roller Pin 2 - B135 Roller 2 - B220 Spring 1 - B308 Spring 4 - B379 Lock 2 - B423 Pin 2 - B888 Bushing	<table border="1" style="width: 100%; border-collapse: collapse;"> <tbody> <tr> <td style="font-size: x-small;">Batco</td> <td style="font-size: x-small;">08-109300</td> </tr> <tr> <td style="font-size: x-small;">BWP</td> <td style="font-size: x-small;">M-K45</td> </tr> <tr> <td style="font-size: x-small;">Euclid</td> <td style="font-size: x-small;">E-3484</td> </tr> <tr> <td style="font-size: x-small;">Leland</td> <td style="font-size: x-small;">K-154</td> </tr> <tr> <td style="font-size: x-small;">Meritor</td> <td style="font-size: x-small;">KIT 8004</td> </tr> <tr> <td style="font-size: x-small;">Midland</td> <td style="font-size: x-small;">CQ67395</td> </tr> <tr> <td style="font-size: x-small;">Spicer</td> <td style="font-size: x-small;">HK44XLS</td> </tr> </tbody> </table>	Batco	08-109300	BWP	M-K45	Euclid	E-3484	Leland	K-154	Meritor	KIT 8004	Midland	CQ67395	Spicer	HK44XLS
	Batco	08-109300														
BWP	M-K45															
Euclid	E-3484															
Leland	K-154															
Meritor	KIT 8004															
Midland	CQ67395															
Spicer	HK44XLS															
	FMS LINING NUMBER(S) 4670 (7-1/2")															