







CAMSHAFT WASHERS

	PART NO.	O.D.	I.D.	THK	REPLACES
	B8721 For Hendrickson "Intraax"	5-3/4"	1-9/16"	.060"	Batco BWP Euclid Leland Meritor Spicer 04-360
	B8718 For Meritor "Q" Brakes	5-13/16"	1-1/2"	.060"	Batco BWP Euclid Leland Meritor Spicer 04-334 M-2634 E-3478 L-2927 1229N2250 29-1339
	B8763 For Eaton 16-1/2" "ES" Brakes	---	1-1/2"	.062"	Batco BWP Eaton Euclid Leland Meritor Spicer 04-357 M-3240 806380 E-5482 L-2963 R627033
	B8781 For Mack "Q" 50,000# Brakes	---	1-41/64"	.060"	Batco BWP Euclid Leland Meritor Spicer 04-338 E-9071 L-3363 1229E4685
	B8784 For Meritor "Q-Plus" Trailer Axles With Fabricated Spider	2-11/16"	1-5/8"	1/4" Cup	Batco BWP Euclid Leland Meritor Spicer 04-321 E-6077 L-3057 1229R4100
	B8787 For Meritor "Q" Trailer Axles With 1-5/8" Camshafts	2-3/8"	1-41/64"	11/32"	Batco BWP Euclid Leland Meritor Spicer 04-362 M-3248 E-9075 L-2944 1229C4137

Copyright 2005 Sirco Industries, Inc.