




BRAKE REPAIR KITS

BENDIX 15" FRONT AXLE BRAKE				
	FF-1		REPLACES	
			FF-1	FF-1A
	2 - B136	Roller Pin	Batco 08-114000	08-114002
	2 - B137	Roller	Bendix 104627	
	1 - B138	Anchor Pin	BWP M-K94	
	1 - B139	Spring	Euclid E-7231	
	2 - B140	Spring	Leland K-297	K-298
			Meritor R507080	
			Midland CQ65519	
			Spicer HK70	
	FF-1A		FMS LINING NUMBER(S)	
	Above Less:		4693 (4")	
	1 - B138	Anchor Pin		

BENDIX 15" FRONT AXLE BRAKE - SPRINGS ONLY				
	FF-1S		REPLACES	
	2 - B139	Spring	Batco	
	4 - B140	Spring	Bendix 104623	
			BWP	
			Euclid E-7232	
			Leland	
			Meritor	
			Midland	
			Spicer	
			FMS LINING NUMBER(S)	
			4693 (4")	

DANA 15" "HA" SERIES STEER AND LIFT AXLE				
	SF-1		REPLACES	
	1 - B142	Spring	Batco 08-116600	
	2 - B151	Retainer	BWP	
	2 - B220	Spring	Euclid E-11493	
	2 - B423	Pin	Leland K-374	
	2 - B586	Roller	Meritor	
			Midland	
			Spicer HK95XLS	
			FMS LINING NUMBER(S)	
			4693 (4")	

Copyright 2005 Sirco Industries, Inc.