



# BRAKE REPAIR KITS


## EATON 15" "EB" AND "ES" SERIES

	<b>EF-1</b>		<b>REPLACES</b>	
	1 - B562	Spring	Batco	08-111300
	2 - B725	Roller	BWP	M-K77
1 - B999	Spring	Eaton	1008306	
		Euclid	E-5139	
			E-1308E	
		Leland	K-263	
		Meritor	R507004	
			MKT1308E	
		Midland	C66917	
			CQ66917	
		Spicer	HK54	
<b>FMS LINING NUMBER(S)</b>				
1308 (4")				
1443TT (4")				

## EATON 15" x 6" "ES" AND "ES-II" REDUCED ENVELOPE FRONT BRAKE

	<b>ES-3</b>		<b>REPLACES</b>	
	2 - B220	Spring	<b>ES-3</b>	
	2 - B430K	Roller	<b>ES-3R</b>	
2 - B431	Retainer	Batco	08-104300	08-104400
2 - B433	Spring	BWP	M-K114	
		Eaton	823141	
		Euclid	E-9141	
		Leland	K-356	
		Meritor	R507086	
		Midland	CQ66947	
		Spicer	HK90XLS	
<b>FMS LINING NUMBER(S)</b>				
4716 (6")				

## EATON 15" "ES-II" FRONT BRAKE

	<b>ES-5</b>		<b>REPLACES</b>	
	2 - B430K	Roller	Batco	08-114700
	2 - B431	Retainer	BWP	
2 - B434	Spring	Eaton		
1 - B871	Spring	Euclid		
		Leland		
		Meritor		
		Midland		
		Spicer		
<b>FMS LINING NUMBER(S)</b>				
4729 (4")				

Copyright 2005 Sirco Industries, Inc.