




BRAKE REPAIR KITS

EATON 15" x 8-5/8" "ES" AND "ES-II" REDUCED ENVELOPE BRAKE DRIVE AXLE				
	ES-4		REPLACES	
	2 - B220	Spring	ES-4	
	2 - B430K	Roller	Batco	08-104330
2 - B431	Retainer	BWP	M-K115	08-104430
1 - B436	Spring	Eaton	815626	
		Euclid	E-9039	
		Leland	K-358	
		Meritor	R507083	
		Midland	CQ66948	
		Spicer	HK91XLS	
	ES-4R		FMS LINING NUMBER(S) 4717 (8-5/8")	
2 - B434	Spring (Replaces B220)			



MACK 15" "Q-PLUS" FRONT BRAKE				
	RF-6		REPLACES	
	2 - B120	Anchor Pin	Batco	08-116030/40
	2 - B161	Retainer	BWP	
2 - B220	Spring	Euclid		K-504K
2 - B423	Pin	Leland		
2 - B888S	Bushing	Meritor		
2 - B911	Roller	Midland		
1 - B957	Spring	Spicer		
		FMS LINING NUMBER(S)		
		4702 (4")	4703 (5")	
		4704 (6")	4705 (7")	

Copyright 2005 Sirco Industries, Inc.