


FRUEHAUF F-2 PARTS

| PART NO. | NOTES | REPLACES |
|--|--|--|
|  SF1005 | Compression Washer Outside Diameter 4" Inside Diameter 1-1/16" Thickness 1/4" | Automann WA 03 BWP M-1809 Dayton 334-455 Euclid E-1021 Flagg FR262 Fruehauf UXA-000003 Meritor R301021 |
|  SF1006 | Outer Washer Outside Diameter 4" Inside Diameter 2" Thickness 1/16" | Automann WA 04 BWP M-2869 Dayton 334-454 Euclid E-2832 Flagg FR293 Fruehauf UXA-000356-002 Meritor R302832 |
|  SF1007 | Adjustable Torque Arm 15-7/16" Center To Center Bushings Not Included Uses SF1009 Torque Arm Bushing Assembly | Automann TR 006 BWP M-2151 Dayton 345-201 Euclid E-2515 Flagg FR254/I Fruehauf UCF-002640-001 Meritor R302515 |
|  SF1008 | Rigid Torque Arm 15-7/16" Center To Center Bushings Not Included Uses SF1009 Torque Arm Bushing Assembly | Automann TR 021 BWP M-2152 Dayton 345-202 Euclid E-2514 Flagg FR271 Fruehauf UXA-000026-001 Meritor R302514 |
|  SF1009/SF1009U | Torque Arm Bushing Assembly Includes: (1) SF1010 Bolt (2) SF1011 Bushing (1) SF1012 Washer (1) SF1013 Washer (1) SR1011 Nut | Automann TRK 6300/UB BWP M-1803 Dayton 334-565 Euclid E-1023/E-9362 Flagg FR266 Fruehauf UXA-0011-900 Meritor R301023/R309362 |
|  SF1010 | Torque Arm Bolt (Solid) Body Diameter 1-1/4" Thread 1" - 14 Length 6" | Automann TRS 3309 BWP M-1804 Dayton 334-566 Euclid E-1018 Flagg FR268 Fruehauf UXA-000016 Meritor R301018 |

Copyright 2005 Sirco Industries, Inc.