





# HUTCHENS REPLACEMENT PARTS

PART NO.	NOTES	REPLACES														
 <p style="text-align: center;"><b>SH1050</b></p>	<p>Cast Equalizer</p> <p>For CH-9600/CH-9700</p> <p>Includes SH1049 Bushing</p>	<table border="0"> <tr><td>Automann</td><td>EQ 028</td></tr> <tr><td>BWP</td><td>M-3482C</td></tr> <tr><td>Dayton</td><td>338-887</td></tr> <tr><td>Euclid</td><td>E-9471</td></tr> <tr><td>Flagg</td><td>H225/I</td></tr> <tr><td>Hutchens</td><td>16290-01</td></tr> <tr><td>Meritor</td><td>R309471</td></tr> </table>	Automann	EQ 028	BWP	M-3482C	Dayton	338-887	Euclid	E-9471	Flagg	H225/I	Hutchens	16290-01	Meritor	R309471
Automann	EQ 028															
BWP	M-3482C															
Dayton	338-887															
Euclid	E-9471															
Flagg	H225/I															
Hutchens	16290-01															
Meritor	R309471															
 <p style="text-align: center;"><b>SH1061</b></p>	<p>Equalizer Bolt Kit</p> <p>For H-9600/H-9700/CH-9600/CH-9700</p> <p>Includes: (2) SH1011 Nut            (2) SH1045 Bolt            (2) SH1046 Sleeve            (1) SH1054 Bolt            (1) SH1055 Nut            (2) SH1062 Washer</p>	<table border="0"> <tr><td>Automann</td><td>TRK 5544A</td></tr> <tr><td>BWP</td><td></td></tr> <tr><td>Dayton</td><td>334-937</td></tr> <tr><td>Euclid</td><td>E-9475</td></tr> <tr><td>Flagg</td><td>H226</td></tr> <tr><td>Hutchens</td><td>16353-01</td></tr> <tr><td>Meritor</td><td>R309475</td></tr> </table>	Automann	TRK 5544A	BWP		Dayton	334-937	Euclid	E-9475	Flagg	H226	Hutchens	16353-01	Meritor	R309475
Automann	TRK 5544A															
BWP																
Dayton	334-937															
Euclid	E-9475															
Flagg	H226															
Hutchens	16353-01															
Meritor	R309475															
 <p style="text-align: center;"><b>SH1053/SH1053U</b></p>	<p>Equalizer Bushing Assembly</p> <p>For H-9600/H-9700/CH-9600/CH-9700</p> <p>Includes: (1) SH1049 Bushing            (1) SH1054 Bolt            (1) SH1055 Nut</p> <p>SH1053U Contains SH1049U Bushing</p>	<table border="0"> <tr><td>Automann</td><td>TRK 5542/UB</td></tr> <tr><td>BWP</td><td></td></tr> <tr><td>Dayton</td><td>334-1272</td></tr> <tr><td>Euclid</td><td>E-9472/E-9473</td></tr> <tr><td>Flagg</td><td></td></tr> <tr><td>Hutchens</td><td></td></tr> <tr><td>Meritor</td><td>R309472/R309473</td></tr> </table>	Automann	TRK 5542/UB	BWP		Dayton	334-1272	Euclid	E-9472/E-9473	Flagg		Hutchens		Meritor	R309472/R309473
Automann	TRK 5542/UB															
BWP																
Dayton	334-1272															
Euclid	E-9472/E-9473															
Flagg																
Hutchens																
Meritor	R309472/R309473															
 <p style="text-align: center;"><b>SH1049/SH1049U</b></p>	<p>Equalizer Bushing</p> <p>For H-9600/H-9700/CH-9600/CH-9700</p> <p>SH1049U Is Polyurethane</p> <p>Outside Diameter 3-1/2"            Inside Diameter 1-1/8"            Length 3-7/8"</p>	<table border="0"> <tr><td>Automann</td><td>TRB 5542/UB</td></tr> <tr><td>BWP</td><td>M-3483</td></tr> <tr><td>Dayton</td><td>321-221/U</td></tr> <tr><td>Euclid</td><td>E-7621/E-8666</td></tr> <tr><td>Flagg</td><td>H227/I/UB</td></tr> <tr><td>Hutchens</td><td>16146-01</td></tr> <tr><td>Meritor</td><td>R307621/R308666</td></tr> </table>	Automann	TRB 5542/UB	BWP	M-3483	Dayton	321-221/U	Euclid	E-7621/E-8666	Flagg	H227/I/UB	Hutchens	16146-01	Meritor	R307621/R308666
Automann	TRB 5542/UB															
BWP	M-3483															
Dayton	321-221/U															
Euclid	E-7621/E-8666															
Flagg	H227/I/UB															
Hutchens	16146-01															
Meritor	R307621/R308666															
 <p style="text-align: center;"><b>SH1054</b></p>	<p>Equalizer Bolt</p> <p>For H-9600/H-9700/CH-9600/CH-9700</p> <p>Thread 1-1/8" - 7            Length 6-7/8"</p>	<table border="0"> <tr><td>Automann</td><td>C 118700 GR8</td></tr> <tr><td>BWP</td><td>M-3484</td></tr> <tr><td>Dayton</td><td>334-739</td></tr> <tr><td>Euclid</td><td>E-7533</td></tr> <tr><td>Flagg</td><td>H221</td></tr> <tr><td>Hutchens</td><td>16150-01</td></tr> <tr><td>Meritor</td><td>R307533</td></tr> </table>	Automann	C 118700 GR8	BWP	M-3484	Dayton	334-739	Euclid	E-7533	Flagg	H221	Hutchens	16150-01	Meritor	R307533
Automann	C 118700 GR8															
BWP	M-3484															
Dayton	334-739															
Euclid	E-7533															
Flagg	H221															
Hutchens	16150-01															
Meritor	R307533															
 <p style="text-align: center;"><b>SH1055</b></p>	<p>Nut</p> <p>Thread 1-1/8" - 7            Hex 1-11/16"            Height 15/16"</p>	<table border="0"> <tr><td>Automann</td><td>LNC 107A</td></tr> <tr><td>BWP</td><td>M-2126</td></tr> <tr><td>Dayton</td><td>334-375</td></tr> <tr><td>Euclid</td><td>E-4358</td></tr> <tr><td>Flagg</td><td>LNC107A</td></tr> <tr><td>Hutchens</td><td>11154-00</td></tr> <tr><td>Meritor</td><td>R304358</td></tr> </table>	Automann	LNC 107A	BWP	M-2126	Dayton	334-375	Euclid	E-4358	Flagg	LNC107A	Hutchens	11154-00	Meritor	R304358
Automann	LNC 107A															
BWP	M-2126															
Dayton	334-375															
Euclid	E-4358															
Flagg	LNC107A															
Hutchens	11154-00															
Meritor	R304358															

Copyright 2005 Sirco Industries, Inc.