

HUTCHENS REPLACEMENT PARTS

PART NO.	NOTES	REPLACES	
 <p>SH1001/SH1001U</p>	<p>Torque Arm Bushing</p> <p>For H-7700/CH-7700</p> <p>SH1001U Is Polyurethane</p> <p>Outside Diameter 1-29/32" Inside Diameter 1" Length 3"</p>	<p>Automann TRB 6326/UB BWP M-1888 Dayton 321-175/U Euclid E-934/E-7453 Flag RBT201/UB Hutchens 722-00 Meritor R30934/R307453</p>	
 <p>SH1026</p>	<p>Torque Arm Bolt</p> <p>For H-7700/H-9700/CH-7700/CH-9700</p> <p>Thread 1" - 14 Length 5"</p>	<p>Automann F 100500 GR5 BWP M-2160 Dayton 334-359 Euclid E-2891 Flag H103 Hutchens 719-02 Meritor R302891</p>	
 <p>SH1027</p>	<p>Flanged Nut</p> <p>For H-7700/H-9700/CH-7700/CH-9700</p> <p>Thread 1" - 14 Hex 1-7/16" Height 7/8"</p>	<p>Automann FLN 107 BWP M-2161 Dayton 334-319 Euclid E-2892 Flag H104 Hutchens 10562-00 Meritor R302892</p>	
 <p>SH1030</p>	<p>Top Plate</p> <p>Fabricated</p> <p>Width 3" Length 7-1/2"</p>	<p>Automann M 852 BWP M-2148 Dayton 338-1367 Euclid E-2907A Flag E303 Hutchens 7029-00 Meritor R302907A</p>	
 <p>SH1032</p>	<p>Bottom Plate</p> <p>For 5" Round Axle</p>	<p>Automann M 8286 BWP M-2149 Dayton 338-415 Euclid E-2909 Flag H115 Hutchens 710-00 Meritor R302909</p>	
 <p>SH1031</p>	<p>Spring Seat</p> <p>For 5" Round Axle</p> <p>For H-7700/H-9700/CH-7700/CH-9700</p> <p>Seat Height 3/4"</p>	<p>Automann M 8284 BWP M-2868 Dayton 338-409 Euclid E-2908 Flag H169/I Hutchens 705-01 Meritor R302908</p>	

Copyright 2005 Sirco Industries, Inc.