







HUTCHENS REPLACEMENT PARTS

PART NO.	NOTES	REPLACES
 SH1060	Center Hanger Under Mount For H-9700	Automann M 8097 BWP Dayton 338-885 Euclid E-9582 Flag Hutchens 16171-01 Meritor R309582
 SH1038	Rear Hanger Under Mount For H-7700/H-9700	Automann M 8298 BWP M-3489 Dayton 338-456 Euclid E-2915A Flag H166/I Hutchens 7703-02 Meritor R302915A
 SH1062	Equalizer Bolt Washer Used In SH1061 Kit Outside Diameter 2" Inside Diameter 1-1/4" Thickness 1/8"	Automann BWP Dayton Euclid E-2548 Flag H256 Hutchens 837-00 Meritor R302548
 SH1023	Delrin Spring Liner Thickness .043" Width 2-7/8" Length 8"	Automann DL 376 BWP M-2872 Dayton GL-294 Euclid E-2842 Flag DL294/DL295 Hutchens 7052-02 Meritor R302842 Reyco T-5166
 SH1016	U-Bolt Washer Heat Treated Outside Diameter 1-3/4" Inside Diameter 15/16" Thickness 1/8"	Automann MUBW 184 BWP M-2136 Dayton 334-150 Euclid E-2546 Flag UBW80 Hutchens 35-00 Meritor R302546 Reyco T-7292
 SH1039	U-Bolt Hi-Nut Grade 8 Thread 7/8" - 14 Across Flats 1-1/4" Height 1-5/32"	Automann DN 5 BWP M-1194 Dayton DN-78 Euclid E-3002A Flag DN5 Hutchens 34-00 Meritor R303002A Reyco 09352-01

Copyright 2005 Sirco Industries, Inc.