



# REYCO 21B PARTS

PART NO.	NOTES	REPLACES
 <b>SR1006</b>	Equalizer Shaft Lock Bolt  Model 21B  Thread                      1" - 8 Length                        2-1/2"	Automann    C 100212 GR5 BWP            M-2808 Dayton        334-209 Euclid         E-1987 Flagg          R111 Meritor        R301987 Reyco         14248-01
 <b>SR1007/SR1007U</b>	Torque Arm Bushing Assembly  Model 21B  Includes:    (2) SR1008    Bushing (1) SR1009    Bolt (2) SR1010    Washer (1) SR1011    Nut	Automann    TRK 6008/UB BWP            M-1765 Dayton        334-252 Euclid         E-1312A/E-9545 Flagg          R003 Meritor        R301312A/R309545 Reyco         TK-18997
 <b>SR1008/SR1008U</b>	Torque Arm Bushing  Model 21B  SR1008U Is Polyurethane  Small Outside Dia.        1-13/16" Large Outside Dia.        2-3/8" Inside Diameter            1" Length                        3"	Automann    TRB 6008/UB BWP            M-1718 Dayton        321-145/U Euclid         E-1160/E-7523 Flagg          R130/UB Meritor        R301160/R307523 Reyco         T-5493
 <b>SR1009</b>	Torque Arm Bolt  Model 21B  Thread                      1" - 14 Length                        6-3/4"	Automann    M 5288 BWP            M-1766 Dayton        334-203 Euclid         E-1166 Flagg          R160 Meritor        R301166 Reyco         T-5492
 <b>SR1010</b>	Torque Arm Washer  Model 21B  Outside Diameter        2-3/4" Inside Diameter         1-1/16" Thickness                  3/16"	Automann    WA 05 BWP            M-1764 Dayton        334-205 Euclid         E-907 Flagg          R159 Meritor        R30907 Reyco         T-2224
 <b>SR1011</b>	Torque Arm Nut  Model 21B  Thread                      1" - 14 Hex                            1-7/16" Height                        7/8"	Automann    LN 107 BWP            M-2941 Dayton        E-1828 Euclid         LN107 Flagg          R30937 Meritor        R30937 Reyco         T-5495