






REYCO 21B PARTS

PART NO.	NOTES	REPLACES
 SR1016	Spring Roller Assembly Model 21B Includes: (1) SR1017 Bolt (1) SR1018 Roller (1) SR1019 Washer (1) SR1020 Nut	Automann SRL 109 BWP M-2819 Dayton 334-201 Euclid E-1975 Flagg R231 Meritor Reyco TK-19011
 SR1017	Spring Roller Bolt Model 21B Thread 1/2" - 20 Length 4-3/4"	Automann F 120500 GR5 BWP Dayton Euclid E-1972 Flagg R202 Meritor R301972 Reyco T-5544
 SR1018	Spring Roller Model 21B Outside Diameter 27/32" Inside Diameter 5/8" Length 3-5/16"	Automann BWP Dayton Euclid E-1971 Flagg R139 Meritor R301971 Reyco T-2106
 SR1019	Lock Washer Model 21B Outside Diameter 29/32" Inside Diameter 17/32" Thickness .061"	Automann BWP Dayton Euclid E-1974 Flagg Meritor R301974 Reyco
 SR1020	Nut Model 21B Thread 1/2" - 20	Automann PNF 104 BWP M-215 Dayton CBN-385 Euclid E-5032 Flagg PNF104 Meritor Reyco T-1704