




# BRAKE REPAIR KITS

<b>EATON 16-1/2" SINGLE ANCHOR PIN BRAKE - FORD</b>			
	<b>EK-3</b>		<b>REPLACES</b>
	2 - B152	Roller Pin	Batco
2 - B769	Spring	BWP	M-K6
2 - B942	Roller	Euclid	E-3801
1 - B983	Spring	Leland	K-316
		Meritor	R507077
		Midland	CQ69004
		Spicer	HK24XLSHM
For High Mount Shoes With Offset Retainer Pin			<b>FMS LINING NUMBER(S)</b>
			4223A (5")
			4317G (6")
			4311J (7")

<b>EATON 16-1/2" "ES-II" "EXTENDED SERVICE" FRONT AXLE BRAKE</b>			
	<b>EF-2</b>		<b>REPLACES</b>
	2 - B430K	Roller	Batco
2 - B431	Retainer	BWP	M-K113
2 - B433	Spring	Eaton	314146
2 - B434	Spring	Euclid	E-10760
		Leland	K-376
		Meritor	R507094
		Midland	CQ65446
		Spicer	HK62
Use With "ES-II" Shoe And "ES" Cams Only			<b>FMS LINING NUMBER(S)</b>
			4719 (5")
			4725 (6")

<b>EATON 16-1/2" "ES" "EXTENDED SERVICE" BRAKE</b>				
	<b>ES-1</b>		<b>REPLACES</b>	
	2 - B430K	Roller	<b>ES-1</b>	<b>K-3</b>
2 - B431	Retainer	Batco	08-114800	E-11318
1 - B432A	Spring	BWP	M-K84	
2 - B769	Spring	Eaton	808330	
		Euclid	E-5481A	
		Euclid	E-4709ES	
		Leland	K-295	
		Meritor	R507057	
		Meritor	MKT4709ES	
		Midland	C65481/CQ65481	
		Spicer	HK63	
<b>K-3</b>		<b>FMS LINING NUMBER(S)</b>		
Spring Kit				
1 - B432A	Spring	4709 (7")		
2 - B769	Spring			
Use Only With "ES" Camshafts				