



BRAKE REPAIR KITS

EATON 16-1/2" "ES-II" "EXTENDED SERVICE" BRAKE																																					
	ES-2		REPLACES																																		
	2 - B430K	Roller																																			
	2 - B431	Retainer																																			
1 - B432A	Spring																																				
2 - B434*	Spring																																				
*Installed Coil End At Top		<table border="1"> <thead> <tr> <th colspan="2">ES-2</th> <th>K-4</th> </tr> </thead> <tbody> <tr> <td>Batco</td> <td>08-114900</td> <td>08-114950</td> </tr> <tr> <td>BWP</td> <td>M-K105</td> <td></td> </tr> <tr> <td>Eaton</td> <td>314147</td> <td></td> </tr> <tr> <td>Euclid</td> <td>E-10244/S</td> <td>E-11319</td> </tr> <tr> <td></td> <td>E-4709ES2</td> <td></td> </tr> <tr> <td>Leland</td> <td>K-375</td> <td></td> </tr> <tr> <td>Meritor</td> <td>R507064</td> <td></td> </tr> <tr> <td></td> <td>MKT4709ES2</td> <td></td> </tr> <tr> <td>Midland</td> <td>C65477/CQ65477</td> <td>CQ65416</td> </tr> <tr> <td>Spicer</td> <td>HK61/SD/XLS</td> <td></td> </tr> </tbody> </table>	ES-2		K-4	Batco	08-114900	08-114950	BWP	M-K105		Eaton	314147		Euclid	E-10244/S	E-11319		E-4709ES2		Leland	K-375		Meritor	R507064			MKT4709ES2		Midland	C65477/CQ65477	CQ65416	Spicer	HK61/SD/XLS			
ES-2		K-4																																			
Batco	08-114900	08-114950																																			
BWP	M-K105																																				
Eaton	314147																																				
Euclid	E-10244/S	E-11319																																			
	E-4709ES2																																				
Leland	K-375																																				
Meritor	R507064																																				
	MKT4709ES2																																				
Midland	C65477/CQ65477	CQ65416																																			
Spicer	HK61/SD/XLS																																				
K-4		FMS LINING NUMBER(S)																																			
Spring Kit		4719 (5") 4725 (6")																																			
1 - B432A	Spring	4709 (7") 4726 (8-5/8")																																			
2 - B434	Spring																																				
Use With "ES-II" Shoe And "ES" Cams Only																																					

EATON 16-1/2" "ES" AND "ES-II" DRIVE, STEER AND TRAILER AXLES				
	ES-12		REPLACES	
	2 - B430K	Roller		
	2 - B431	Retainer		
1 - B432A	Spring			
2 - B434	Spring			
2 - B769	Spring			
Contains Both "ES" And "ES-II" Style Retainer Spring		K-495		
Use B434 Only On "ES-II" Shoes		FMS LINING NUMBER(S)		
		4709 (7")		

