




BRAKE REPAIR KITS

EATON RETRO-FIT 16-1/2" BRAKE FOR MERITOR "Q"		
	EQ-1	REPLACES
	2 - B120 Anchor Pin 2 - B220 Spring 1 - B349 Heavy Duty Spring 2 - B423 Retainer 2 - B431 Retainer 2 - B888S Bushing 2 - B911 Roller	Batco 08-115400/05 BWP Euclid E-8925 E-8925SHD Leland K-322 Meritor R507062 Midland CQ65479 Spicer HK67XLS Top Spec 5-3319
		FMS LINING NUMBER(S) 4708 (7")

EATON RETRO-FIT 16-1/2" FOR MERITOR "P"		
	ET-1	REPLACES
	1 - B349 Heavy Duty Spring 2 - B423 Pin 2 - B431 Retainer 4 - B793 Lock 2 - B887 Anchor Pin 2 - B888S Bushing 2 - B911 Roller 4 - B988 Washer	Batco 08-115500/05 BWP Euclid Leland Meritor Midland Spicer HK69XLS Top Spec 5-3320
		FMS LINING NUMBER(S) 4708 (7")

EATON RETRO-FIT 16-1/2" BRAKE FOR FRUEHAUF "XEM"		
	EX-1	REPLACES
	2 - B220 Spring 2 - B277 Anchor Pin 1 - B349 Heavy Duty Spring 2 - B423 Pin 2 - B431 Retainer 2 - B888S Bushing 2 - B911 Roller	Batco 08-115800/05 BWP Euclid E-8923 Leland Meritor R507061 Midland CQ65478 Spicer HK65SD Top Spec 5-3321
		FMS LINING NUMBER(S) 4708 (7")