




BRAKE REPAIR KITS

FRUEHAUF (MODIFIED #5) 16-1/2" EARLY MODEL BRAKE				
	FK-2		REPLACES	
		2 - B151 Retainer 2 - B423 Pin 2 - B832 Anchor Pin 2 - B911 Roller 2 - B932 Lock 1 - B971 Spring	FK-2	FK-2HD
			Batco 08-100601/05 BWP Euclid KIT 5 Fruehauf Leland K-58 Meritor R507013 Midland Spicer	08-100661/65 M-K5 MBCBK0014
	FK-2HD		FMS LINING NUMBER(S)	
	1 - B728 Heavy Duty Spring (Replaces B971)	4515 (7") 4551 (8-5/8")		

FRUEHAUF "PROPAR" 16-1/2" BRAKE				
	FK-1		REPLACES	
		2 - B423 Pin 2 - B495 Bushing 2 - B498 Retainer 2 - B832 Anchor Pin 2 - B911 Roller 2 - B932 Lock 1 - B971 Spring	FK-1	FK-1HD
			Batco 08-100600/04 BWP Euclid E-2121 Fruehauf MBCBK0013 Leland K-43 Meritor R507011 Midland CQ67316 Spicer HK17XLS	08-100660/64 M-K8 E-2121HD ACC001996-902 R507012 CQ67399
	FK-1HD		FMS LINING NUMBER(S)	
	1 - B728 Heavy Duty Spring (Replaces B971)	4515 (7") 4551 (8-5/8")		

FRUEHAUF "PROPAR" 16-1/2" (EARLY MODEL) "XEM"				
	XK-1		REPLACES	
		2 - B151 Retainer 2 - B220 Spring 1 - B302 Spring 2 - B377 Anchor Pin 2 - B423 Pin 2 - B495 Bushing 2 - B911 Roller 2 - B932 Lock	XK-1	XK-1HD
			Batco 08-109001/05 BWP Euclid E-4880S Leland K-127 Meritor R507006 Midland CQ67401 Spicer	08-109031/35 M-K41 E-4880SHD R507007 CQ66875 HK31XLS
	XK-1HD		FMS LINING NUMBER(S)	
	1 - B349 Heavy Duty Spring (Replaces B302)	4515 (7") 4551 (8-5/8")		