



BRAKE REPAIR KITS


MACK 16-1/2" BRAKE WITH BUSHED HEAVY DUTY SHOE

	TK-7		REPLACES		
	2 - B151 Retainer 4 - B211 Bushing 2 - B311 Anchor Pin 2 - B423 Pin 4 - B501 Seal 4 - B793 Lock 2 - B861 Lock 2 - B911 Roller 1 - B971 Spring		TK-7	TK-7HD	
			Batco 08-108200/05 BWP Euclid Leland Meritor R509004 Midland Spicer	08-108260/65 M-K56 E-1607HD K-46 R509409 CQ67357 HK75SD	
	TK-7HD		FMS LINING NUMBER(S)		
	1 - B728 Heavy Duty Spring (Replaces B971)		4549C (4") 4524B (5") 4514G (6") 4515E (7")		

MACK WITH MERITOR 16-1/2" BRAKE

	MK-1HD		REPLACES		
	2 - B151 Retainer 4 - B211 Bushing 2 - B311 Anchor Pin 2 - B423 Pin 4 - B501 Seal 1 - B728 Spring 4 - B793 Lock 2 - B861 Lock 2 - B922 Roller		Batco 08-108300 BWP M-K54 Euclid E-2675HD Leland K-77 Meritor R509406 Midland CQ67356 Spicer HK19SD		
			FMS LINING NUMBER(S)		
			4625B (7")		

MACK WITH MERITOR "Q" BRAKE 50,000 LB. REAR AXLE

	MK-2		REPLACES		
	2 - B122 Anchor Pin 2 - B151 Retainer (or B161) 2 - B221 Spring 1 - B349 Heavy Duty Spring 2 - B421* Lock 2 - B422* Pin 2 - B423 Pin 2 - B888S Bushing 2 - B924 Roller		MK-2	MK-2HD	
			Batco 08-111500 BWP Euclid Leland Meritor Midland Spicer	08-111560 M-K93 E-5086 K-293M KIT 8026HD CQ62767 HK82SD	
	MK-2HD		FMS LINING NUMBER(S)		
	1 - B728 Heavy Duty Spring (Replaces B349)		4515H (7")		
	* Not Available Separately				

Copyright 2005 Sirco Industries, Inc.