


BRAKE CAMSHAFTS - DRIVE AXLE

Meritor



LH	RH	A	B	C	NOTES	REPLACES
C880L		14-1/8"	—	—	"P" & "Q"	Batco 04-451422 BWP Euclid E-6880 Leland L-2402 Meritor 18-817 Midland Spicer
	C881R				Camshaft Kit B8646	Batco 04-451421 BWP Euclid E-6881 Leland L-2401 Meritor 18-816 Midland Spicer
C711L		REPLACED BY C711BL			"P" & "Q"	Batco 04-451562 BWP M-1570L Euclid E-4711A Leland Meritor 18-819 Midland Spicer
	C710R	15-3/4"	—	—	Camshaft Kit B8646	Batco 04-451561 BWP M-1570R Euclid E-4710A Leland Meritor 18-818 Midland Spicer
		REPLACED BY C710BR				
C711BL		15-3/4"	—	—	"Q-Plus"	Batco BWP Euclid E-4711B Leland Meritor R607090 Midland Spicer
	C710BR				Camshaft Kit B8707	Batco BWP Euclid E-4710B Leland Meritor R607089 Midland Spicer
C715L		REPLACED BY C715AL				Batco 04-571762 BWP Euclid E-4715 Leland L-2439 Meritor 2210R5712 Midland Spicer 17-573
	C714R	17-3/4"	2-7/32"	—		Batco 04-571761 BWP Euclid E-4714 Leland L-2438 Meritor 2210Q5711 Midland Spicer 17-572
		REPLACED BY C714AR				
C715AL		17-3/4"	2-7/32"	—	"Q-Plus"	Batco BWP Euclid E-4715A Leland Meritor R607094 Midland Spicer
	C714AR				Camshaft Kit B8707	Batco BWP Euclid E-4714A Leland Meritor R607093 Midland Spicer
C413L		REPLACED BY C413AL				Batco 04-571862 BWP M-3178L Euclid E-2413 Leland L-262 Meritor CS41162 Midland Spicer 17-579
	C412R	18-5/8"	2-7/32"	—		Batco 04-571861 BWP M-3178R Euclid E-2412 Leland L-261 Meritor CS41163 Midland Spicer 17-578
		REPLACED BY C412AR				M16WK111-4 M16WK110-4