



# BRAKE REPAIR KITS


## DEXTER 12-1/4" WITH 1" ANCHOR PIN

		LB-1	REPLACES	
	2 - B132	Pin	Batco	08-107400
	2 - B133	Roller	BWP	M-K12
	2 - B216	Anchor Pin	Dexter	K71-98
	1 - B307	Spring	Euclid	E-2402HD
	2 - B358	Retainer	Leland	K-352
	2 - B362	Bushing	Meritor	R507015
	2 - B379	Lock	Midland	CQ67398
	4 - B380	Lock	Spicer	HK43XLS
	4 - B392	Washer		
FMS LINING NUMBER(S)				
4700 (4") 4661C (5")				

## DEXTER 12-1/4" WITH 1-1/4" ANCHOR PIN AND ROLLER

		LB-10D	REPLACES	
	2 - B120	Anchor Pin	Batco	08-104800
	2 - B151	Retainer	BWP	
	2 - B220	Spring	Euclid	
	1 - B307	Spring	Leland	K-353
	2 - B423	Pin	Meritor	
	2 - B888	Bushing	Midland	
	2 - B911	Roller	Spicer	
FMS LINING NUMBER(S)				
4661 (5") 4536 (5-1/2") 4692 (7-1/2")				

## DEXTER 12-1/4" "PQ" BRAKE

		LB-3D	REPLACES	
	2 - B120	Anchor Pin	Batco	08-104700
	2 - B132	Roller Pin	BWP	M-K112
	2 - B133	Roller	Euclid	E-10875
	2 - B220	Spring	Leland	K-369
	1 - B307	Spring	Meritor	R507095
	2 - B379	Lock	Midland	
	2 - B423	Pin	Spicer	HK58XLS
	2 - B888S	Stainless Bushing		
FMS LINING NUMBER(S)				
4700 (4") 4661C (5") 4591 (7-1/2")				

Copyright 2005 Sirco Industries, Inc.