







# CAMSHAFT BUSHINGS

PART NO.	NOTES	REPLACES
 <b>B8698</b>	Outside Diameter 2" Inside Diameter 1-5/8" Length 1-3/16"  Nylon  For Eaton "501" Brake	Batco 02-224 BWP M-2621 Eaton 1008412 Euclid E-2690A Leland L-2382 Meritor R617005 Spicer 28-1238
 <b>B805</b>	Outside Diameter 2" Inside Diameter 1-5/8" Length 1-1/2"  Bronze  For Spicer 16-1/2" Brakes With 1-5/8" Cam Journal	Batco 02-256 BWP M-3747 Euclid E-9789 Leland L-3127 Meritor R627034 Spicer M16HD106
 <b>B8636</b>	Outside Diameter 2-1/8" Inside Diameter 1-1/2" Length 1"  Nylon  For Use In B8696	Batco 03-212 BWP M-1550 Euclid E-2361 Leland L-1730 Meritor 1225R1058 Spicer 27-1197
 <b>B8699</b>	Outside Diameter 2-15/32" Inside Diameter 1-1/2" Length 1-1/2"  Nylon  For Spicer Late Model	Batco 03-210 BWP M-2622 Euclid E-2517 Leland L-1711 Meritor R617008 Spicer 27-1191 M10WJ100
 <b>B8606</b>	Outside Diameter 2-15/32" Inside Diameter 1-1/2" Length 1-3/4"  Nylon  For Standard Forge And Spicer	Batco 03-208 BWP M-582 Euclid E-2102 Leland Meritor R617002 Spicer 27-1195 M10WJ107 Std Forge 405128
 <b>B8606A</b>	Outside Diameter 2-15/32" Inside Diameter 1-1/2" Length 1-3/4"  Greaseless Nylatron  Replaces B8606	Batco BWP M-3748 Euclid E-9792A Leland L-3146 Meritor Spicer M10WJ237X

Copyright 2005 Sirco Industries, Inc.