


# CAMSHAFT WASHERS

	PART NO.	O.D.	I.D.	THK	REPLACES
	<b>B8630</b>	2"	1-9/64"	.032"	Batco 04-308 BWP M-1409 Eaton 23570 Euclid E-1781 Leland L-1608 Meritor R627006 Spicer 29-1320
	For Eaton Brakes				
	<b>B8629</b>	2"	1-9/64"	.060"	Batco 04-307 BWP M-1408 Eaton 35428 Euclid E-1782 Leland L-1609 Meritor R627005 Spicer 29-1321
	For Eaton Brakes				
	<b>B8786</b>	2-1/4"	1-5/8"	1/32"	Batco 04-361 BWP Euclid E-9074 Leland L-3068 Meritor 1229B4136 Spicer
	For Meritor 16-1/2" Diameter "Q-Plus" Brakes				
	<b>B960</b>	2-1/4"	1-5/8"	1/16"	Batco 04-358 BWP M-1402A Euclid E-2411A Leland L-2947 Meritor 1229X3118 Spicer 29-1312
	For Meritor 4000-6000 Trailer Axle				
<b>B8605</b>	2-1/4"	1-17/32"	.032"	Batco 04-301 BWP M-580 Euclid E-581 Leland L-192 Meritor 1229Q771 Spicer 29-1308	
Universal For 1-1/2" Diameter Camshafts					
<b>B8632</b>	2-1/4"	1-17/32"	3/32"	Batco 04-328 BWP M-1413 Euclid E-2409 Leland L-1371 Meritor R627025 Spicer 29-1326 Std Forge 403149	
For Standard Forge 12-1/4" Brakes					

Copyright 2005 Sirco Industries, Inc.