


CAMSHAFT WASHERS

	PART NO.	O.D.	I.D.	THK	REPLACES
	B8607	2-1/4"	1-17/32"	.060"	Batco 04-302 BWP M-583 Euclid E-580 Leland L-193 Meritor 1229R122 Spicer 29-1307
	Universal For 1-1/2" Diameter Camshafts				
	B8752	2-1/4"	1-1/4"	1/16"	Batco 04-350 BWP M-3353 Eaton 1005202 Euclid E-5137 Leland L-2832 Meritor R627031 Spicer 29-1344
	For Eaton 15" x 4" Front Brakes				
	B8753	2-1/4"	1-1/4"	1/32"	Batco 04-351 BWP M-3354 Eaton 1005203 Euclid E-5138 Leland L-2833 Meritor R627032 Spicer 29-1346
	For Eaton 15" x 4" Front Brakes				
	B8757	2-3/8"	1-9/32"	1/8"	Batco 04-347 BWP M-2637 Euclid E-3476 Leland L-1747 Meritor 1229Q277 Spicer 29-1330
	For Meritor 15" x 4" "T" Brakes				
B8719	2-3/8"	1-1/2"	.111"	Batco 04-322 BWP M-2638 Euclid E-3479 Leland L-2928 Meritor 1229S2697 Spicer	
For Meritor "Q" Brakes					
B8785	2-3/8"	1-5/8"	3/32"	Batco 04-333 BWP Euclid E-9072 Leland L-3058 Meritor 1229S4101 Spicer	
For Use With B8783 Bushing					

Copyright 2005 Sirco Industries, Inc.