







CAMSHAFT WASHERS

	PART NO.	O.D.	I.D.	THK	REPLACES
	B811	3-1/8"	1-33/64"	.065"	Batco 04-339 BWP M-2643 Euclid E-3473 Leland L-1724 Meritor 1229E811 Spicer 29-1337
	For Meritor 15" x 4" "T" Brakes				
	B8608	3-7/8"	1-1/2"	1/16"	Batco 04-300 BWP M-584 Euclid E-656 Leland L-202 Meritor 1229G1463 Spicer 29-1310
	For 1-1/2" Diameter Camshafts				
	B8765	3-7/8"	1-1/2"	.063"	Batco 04-335 BWP Euclid L-2926 Leland 1229L844 Meritor 29-1340 Spicer
	For Meritor "P" 1-1/2" Diameter Camshafts				
	B8631	3-7/8"	1-17/32"	1/16"	Batco 04-327 BWP M-1412 Euclid E-2404 Leland L-1372 Meritor R627024 Spicer 29-1319 M10HS115 Std Forge 403150
	For Standard Forge 12-1/4" Brakes				
	B801	2-7/16"	1-11/16"	.060"	Batco M-3986 BWP E-10801 Euclid Leland R627044 Meritor M10HS147 Spicer
	Spicer With 1-5/8" Cam Journal				
	B961	3-7/8"	1-5/8"	1/16"	Batco 04-359 BWP Euclid E-9073 Leland L-2945 Meritor 1229A4135 Spicer
	For Meritor 16-1/2" "Q-Plus" Brakes				

Copyright 2005 Sirco Industries, Inc.