


CAMSHAFT LOCKS

	PART NO.	O.D.	I.D.	THK	REPLACES
	B794	---	31/32"	3/32"	Batco 04-356 BWP Euclid E-9076 Leland L-2940 Meritor 1229J4092 Spicer
	For 15" x 4" "Q" And 16-1/2" "P" Brakes				
	B793	---	1-1/8"	1/16"	Batco 01-482 BWP M-1523 Euclid E-801 Leland L-397 Meritor 1229X1116 Spicer 34-1525
	For Meritor 4000-6000 Trailer Axles				
	B8689	---	1-5/32"	3/32"	Batco 01-492 BWP M-1512 Euclid E-5093 Leland L-331 Meritor 1229D2942 Spicer 34-1547
	For Meritor 15" x 4" "T" And 16-1/2" "Q" Brakes				
	B795	---	1-5/16"	1/16"	Batco M-2648 BWP E-2720 Euclid Leland R627027 Meritor 29-1306 Spicer
	For Hendrickson 16-1/2" "Intraax" Brakes				
B8691	---	1-3/8"	3/32"	Batco 04-318 BWP M-3496 Euclid E-4736 Leland L-2900 Meritor 1229Q2851 Spicer	
For Meritor Drive Axles					
B8604	---	1-31/64"	1/16"	Batco 04-310 BWP M-579 Euclid E-526 Leland L-137 Meritor 1229Z1118 Spicer 29-1301	
Universal For 1-1/2" Diameter Camshafts					

Copyright 2005 Sirco Industries, Inc.