





FIFTH WHEEL COMPONENTS

PART NO.	NOTES	REPLACES										
 <p style="text-align: center;">700</p>	<p>Trailer King Pin</p> <p>3/8" Weld-On</p> <p>AISI 8630 H Alloy Steel</p> <p>Hardened To 302-363 BHN</p> <p>100% Magna Fluxed</p>	<table border="0"> <tr> <td>Batco</td> <td>11-0212</td> </tr> <tr> <td>BWP</td> <td>M-698</td> </tr> <tr> <td>Euclid</td> <td>E-700</td> </tr> <tr> <td>Holland</td> <td>KP-T809F</td> </tr> <tr> <td>Leland</td> <td>L-345</td> </tr> </table>	Batco	11-0212	BWP	M-698	Euclid	E-700	Holland	KP-T809F	Leland	L-345
Batco	11-0212											
BWP	M-698											
Euclid	E-700											
Holland	KP-T809F											
Leland	L-345											
 <p style="text-align: center;">702</p>	<p>King Pin Lock</p>	<table border="0"> <tr> <td>Batco</td> <td>11-0198</td> </tr> <tr> <td>BWP</td> <td>M-770</td> </tr> <tr> <td>Euclid</td> <td>E-702</td> </tr> <tr> <td>Holland</td> <td>GL-030-3000</td> </tr> <tr> <td>Leland</td> <td>L-3391</td> </tr> </table>	Batco	11-0198	BWP	M-770	Euclid	E-702	Holland	GL-030-3000	Leland	L-3391
Batco	11-0198											
BWP	M-770											
Euclid	E-702											
Holland	GL-030-3000											
Leland	L-3391											
 <p style="text-align: center;">710</p>	<p>Polyethylene Fifth Wheel Disk And Lock</p>	<table border="0"> <tr> <td>Butler</td> <td>SD 003</td> </tr> </table>	Butler	SD 003								
Butler	SD 003											
 <p style="text-align: center;">710-2</p>	<p>Lock</p>	<table border="0"> <tr> <td>Butler</td> <td>SD 002</td> </tr> </table>	Butler	SD 002								
Butler	SD 002											