







FRUEHAUF F-2 PARTS

PART NO.	NOTES	REPLACES	
 SF1011/SF1011U	Torque Arm Bushing SF1011U Is Polyurethane Outside Diameter 2-3/16" Inside Diameter 1-1/4" Overall Length 2-3/8"	Automann TRB 6300/UB BWP M-1818 Dayton 321-177/U Euclid E-927/E-7433 Flagg RBT200/UB Fruehauf UXA-000011 Meritor R30927/R307433	
 SF1012	Compression Washer Outside Diameter 2-1/2" Inside Diameter 1-1/16" Thickness 1/4"	Automann WA 02 BWP M-1805 Dayton 334-568 Euclid E-1074 Flagg FR261 Fruehauf UXA-000002 Meritor R301074	
 SF1013	Outer Washer Outside Diameter 2-1/2" Inside Diameter 1-5/16" Thickness 1/16"	Automann WA 01 BWP M-2870 Dayton SFW-125 Euclid E-2833 Flagg FR292 Fruehauf UXA-000356-001 Meritor R302833	
 SR1011	Lock Nut Thread 1" - 14 Hex 1-7/16" Height 7/8"	Automann LN 107 BWP M-2941 Dayton Euclid E-1828 Flagg LN107 Fruehauf FSP-00602PK9 Meritor R30937	
 SF1014	Spring Saddle For Multi-Leaf Springs Only	Automann M 470 BWP Dayton 338-1107 Euclid E-2840 Flagg E112 Fruehauf UCE-008801-001 Meritor R302840	
 SF1015	Spring Saddle For Single Leaf Springs Only	Automann M 471 BWP Dayton 338-1108 Euclid E-2839 Flagg FR209 Fruehauf UCC-005998-001 Meritor R302839	