







HUTCHENS REPLACEMENT PARTS

PART NO.	NOTES	REPLACES
 SH1009	Equalizer Step Bolt For H-2200/H-7600/H-7700/CH-7600 And CH-7700 Diameter 3/4" Length 6" Thread 5/8" - 18	Automann TRS 4413 BWP M-1453 Dayton 334-366 Euclid E-2000 Flagg H110 Hutchens 7016-01 Meritor R302000
 SH1010	Tab Lock	Automann MH 456 BWP M-1454 Dayton 334-360 Euclid E-2001 Flagg H105 Hutchens 729-00 Meritor R302001
 SH1011	Nut Thread 5/8" - 18 Hex 15/16" Height 17/32"	Automann PNF 106 BWP M-1455 Dayton SLN-104 Euclid E-2002 Flagg LN104 Hutchens 37-03 Meritor R302002
 SH1045	Rebound Bolt Thread 5/8" - 18 Length 4-1/2"	Automann F 580412 GR5 BWP Dayton Euclid E-3415 Flagg B1324-43* Hutchens 759-00 Meritor R303415 * Coarse Thread
 SH1046	Spacer Sleeve Outside Diameter 7/8" Inside Diameter 21/32" Length 3-7/32"	Automann MH 558 BWP Dayton 334-361 Euclid E-3416 Flagg H156 Hutchens 756-00 Meritor R303416
 SH1048	Fabricated Equalizer For H-9700 Includes SH1049 Bushing	Automann EQ 019 BWP M-3482 Dayton 338-886 Euclid E-7532 Flagg H220/I Hutchens 16158-01 Meritor R307532