


# HUTCHENS REPLACEMENT PARTS



TYPE 1



TYPE 2

PART NO.	NOTES	REPLACES														
<p>TYPE 1</p> <p><b>SH1041</b></p>	<p>Adjustable Torque Arm</p> <p>For H-7700/H-9700/CH-7700/CH-9700</p> <p>Length 16"</p> <p>Bushing Number SH1001/SH1001U</p> <p>Bushing Assembly SH1040/SH1040U</p>	<table border="0"> <tr><td>Automann</td><td>TR 019</td></tr> <tr><td>BWP</td><td>M-2141</td></tr> <tr><td>Dayton</td><td>345-238</td></tr> <tr><td>Euclid</td><td>E-3276</td></tr> <tr><td>Flagg</td><td>H106/I</td></tr> <tr><td>Hutchens</td><td>16398-02/713-02</td></tr> <tr><td>Meritor</td><td>R303276</td></tr> </table>	Automann	TR 019	BWP	M-2141	Dayton	345-238	Euclid	E-3276	Flagg	H106/I	Hutchens	16398-02/713-02	Meritor	R303276
Automann	TR 019															
BWP	M-2141															
Dayton	345-238															
Euclid	E-3276															
Flagg	H106/I															
Hutchens	16398-02/713-02															
Meritor	R303276															
<p>TYPE 1</p> <p><b>SH1043</b></p>	<p>Adjustable Torque Arm</p> <p>For H-7700/H-9700/CH-7700/CH-9700</p> <p>Length 17-1/4"</p> <p>Bushing Number SH1001/SH1001U</p> <p>Bushing Assembly SH1040/SH1040U</p>	<table border="0"> <tr><td>Automann</td><td>TR 007</td></tr> <tr><td>BWP</td><td>M-2142</td></tr> <tr><td>Dayton</td><td>345-191</td></tr> <tr><td>Euclid</td><td>E-3390</td></tr> <tr><td>Flagg</td><td>H107</td></tr> <tr><td>Hutchens</td><td>16398-17</td></tr> <tr><td>Meritor</td><td>R303390</td></tr> </table>	Automann	TR 007	BWP	M-2142	Dayton	345-191	Euclid	E-3390	Flagg	H107	Hutchens	16398-17	Meritor	R303390
Automann	TR 007															
BWP	M-2142															
Dayton	345-191															
Euclid	E-3390															
Flagg	H107															
Hutchens	16398-17															
Meritor	R303390															
<p>TYPE 1</p> <p><b>SH1042</b></p>	<p>Adjustable Torque Arm</p> <p>For H-7700/H-9700/CH-7700/CH-9700</p> <p>Length 19-1/4"</p> <p>Bushing Number SH1001/SH1001U</p> <p>Bushing Assembly SH1040/SH1040U</p>	<table border="0"> <tr><td>Automann</td><td>TR 004</td></tr> <tr><td>BWP</td><td>M-2143</td></tr> <tr><td>Dayton</td><td>345-164/I</td></tr> <tr><td>Euclid</td><td>E-3277</td></tr> <tr><td>Flagg</td><td>H108/I</td></tr> <tr><td>Hutchens</td><td>16398-04/713-05</td></tr> <tr><td>Meritor</td><td>R303277</td></tr> </table>	Automann	TR 004	BWP	M-2143	Dayton	345-164/I	Euclid	E-3277	Flagg	H108/I	Hutchens	16398-04/713-05	Meritor	R303277
Automann	TR 004															
BWP	M-2143															
Dayton	345-164/I															
Euclid	E-3277															
Flagg	H108/I															
Hutchens	16398-04/713-05															
Meritor	R303277															
<p>TYPE 2</p> <p><b>SH1029</b></p>	<p>Rigid Torque Arm</p> <p>For H-7700/H-9700/CH-7700/CH-9700</p> <p>Length 19-1/4"</p> <p>Bushing Number SH1001/SH1001U</p> <p>Bushing Assembly SH1040/SH1040U</p>	<table border="0"> <tr><td>Automann</td><td>TR 005</td></tr> <tr><td>BWP</td><td>M-2144</td></tr> <tr><td>Dayton</td><td>345-167/I</td></tr> <tr><td>Euclid</td><td>E-2899</td></tr> <tr><td>Flagg</td><td>H167</td></tr> <tr><td>Hutchens</td><td>715-00</td></tr> <tr><td>Meritor</td><td>R302899</td></tr> </table>	Automann	TR 005	BWP	M-2144	Dayton	345-167/I	Euclid	E-2899	Flagg	H167	Hutchens	715-00	Meritor	R302899
Automann	TR 005															
BWP	M-2144															
Dayton	345-167/I															
Euclid	E-2899															
Flagg	H167															
Hutchens	715-00															
Meritor	R302899															
 <p><b>SH1040/SH1040U</b></p>	<p>Torque Arm Bushing Assembly</p> <p>For H-7700/CH-7700</p> <p>Includes: (1) SH1001 Bushing (1) SH1026 Bolt (1) SH1027 Nut</p> <p>SH1040U Contains SH1001U Bushing</p>	<table border="0"> <tr><td>Automann</td><td>TRK 6326/UB</td></tr> <tr><td>BWP</td><td>M-2159</td></tr> <tr><td>Dayton</td><td>334-344</td></tr> <tr><td>Euclid</td><td>E-3079</td></tr> <tr><td>Flagg</td><td>H112</td></tr> <tr><td>Hutchens</td><td></td></tr> <tr><td>Meritor</td><td>R303079/R309486</td></tr> </table>	Automann	TRK 6326/UB	BWP	M-2159	Dayton	334-344	Euclid	E-3079	Flagg	H112	Hutchens		Meritor	R303079/R309486
Automann	TRK 6326/UB															
BWP	M-2159															
Dayton	334-344															
Euclid	E-3079															
Flagg	H112															
Hutchens																
Meritor	R303079/R309486															