




BRAKE REPAIR KITS

MERITOR 16-1/2" BRAKE WITH BUSHED HEAVY DUTY SHOE				
	TK-7		REPLACES	
	2 - B151	Retainer		
	4 - B211	Bushing		
	2 - B311	Anchor Pin		
	2 - B423	Pin		
	4 - B501	Seal		
	4 - B793	Lock		
	2 - B861	Lock		
	2 - B911	Roller		
	1 - B971	Spring		
	TK-7HD			
	1 - B728	Heavy Duty Spring (Replaces B971)	FMS LINING NUMBER(S)	
			4549C (4") 4524B (5") 4514G (6") 4515E (7")	

MERITOR 16-1/2" "P" AND EARLY STANDARD FORGE BRAKE				
	TK-1		REPLACES	
	2 - B151	Retainer		
	2 - B251	Anchor Pin		
	2 - B423	Pin		
	4 - B501	Seal		
	4 - B793	Lock		
	2 - B861	Lock		
	2 - B911	Roller		
	1 - B971	Spring		
	TK-1HD			
	1 - B728	Heavy Duty Spring (Replaces B971)	FMS LINING NUMBER(S)	
			4549C (4") 4524B (5") 4514G (6") 4515E (7") 4551E (8-5/8") 4567A (10")	

16-1/2" "Q", "Q-PLUS", "FC", "XLII", "INTRAAX" BRAKE - PREMIUM				
	QK-1MP		REPLACES	
	2 - B120	Anchor Pin		
	2 - B161	Retainer		
	2 - B220	Spring		
	1 - B302	Spring		
	2 - B423	Pin		
	2 - B888S	Bushing		
	2 - B911	Roller		
	QK-1MPHD			
	1 - B349	Heavy Duty Spring (Replaces B302)	FMS LINING NUMBER(S)	
			4524B (5") 4720 (5") 4514G (6") 4715 (6") 4515E (7") 4707 (7") 4718 (8") 4551E (8-5/8") 4711 (8-5/8") 4549C/4514G (10")	

Copyright 2005 Sirco Industries, Inc.