


# BRAKE REPAIR KITS

## BPW - BERGISCHE ACHSEN 16.53" CHASSIS BRAKE

	<b>KK-1</b>	<b>REPLACES</b>	
	Full Kit Sold Only As A Kit	KK-1	KK-1A
		Batco BWP Euclid Jost Leland Meritor Midland Spicer	R9000B K-379
	<b>KK-1A</b>	FMS LINING NUMBER(S) 1477TT (7.09")	
	Minor Kit Sold Only As A Kit		

## EATON 18" SINGLE ANCHOR PIN BRAKE - CAST SHOES

	<b>EK-2</b>	<b>REPLACES</b>		
	2 - B053    Roller 2 - B154    Roller Pin 2 - B770    Spring 1 - B982    Spring	Batco      08-109600 BWP        M-K58 Eaton     1005006 Euclid     E-2821 Leland     K-275 Meritor    R507072 Midland    CQ67406 Spicer     HK26		
		FMS LINING NUMBER(S) 4527B (7")		

## MERITOR 18" BRAKE WITH CAST SHOES

	<b>RK-1 (OLD STYLE)</b>	<b>REPLACES</b>	
	4 - B211S    Bushing 2 - B311     Anchor Pin 4 - B501     Seal 4 - B793     Lock 2 - B861     Lock 2 - B923     Roller 1 - B972     Spring 2 - B973     Retainer	RK-1	RK-2
		Batco      08-109830 BWP        M-K59 Euclid     E-3518 Leland     K-274 Meritor    KIT 9179 Midland    CQ67407 Spicer     HK68	08-109800  E-3992 K-281 R509408 CQ67408 HK76
	<b>RK-2 (NEW STYLE)</b>	FMS LINING NUMBER(S) 4471B (7")	
	2 - B595S    Bushing 1 - B974     Spring (Replaces B972)  Less (2) - B973		