


BRAKE CAMSHAFTS - DRIVE AXLE

Meritor "Q" And "Q-Plus"



"A" Dimension: under head to beginning of lock ring groove.

1-1/2" Dia. - 28 Spline

LH	RH	A	B	C	NOTES	REPLACES	
C729L		REPLACED BY C669L			"Q"	Batco 04-461312 BWP M-2607L Euclid E-4729L Leland L-2883	Meritor 2210L5342 Midland Spicer 18-837
		12-15/16"	-	-	Camshaft Kits		
					B8707 B8771	Batco 04-461311 BWP M-2607R Euclid E-4728R Leland L-2882	Meritor 2210K5341 Midland Spicer 18-836
C728R		REPLACED BY C670R			B8745 (Mack)		
C669L		REPLACED BY C670R			"Q-Plus"	Batco 04-481312 BWP M-2607L Euclid E-9669 Leland L-3403	Meritor 2210U7587 Midland CS41156 Spicer 18-527
		12-15/16"	-	-	Camshaft Kits		
					B8707 B8771 B8745 (Mack)	Batco 04-481311 BWP M-2607R Euclid E-9670 Leland L-3402	Meritor 2210T7586 Midland CS41157 Spicer 18-526
C670R		REPLACED BY C670R			B8745 (Mack)		
C731L		REPLACED BY C595L			"Q"	Batco 04-461332 BWP M-2597L Euclid E-4731 Leland L-2885	Meritor 2210D5334 Midland Spicer 18-821
		13-7/32"	-	-	Camshaft Kits		
					B8707 B8771	Batco 04-461331 BWP M-2597R Euclid E-4730 Leland L-2884	Meritor 2210C5333 Midland Spicer 18-820
C730R		REPLACED BY C594R			B8745 (Mack)		
C595L		REPLACED BY C594R			"Q-Plus"	Batco 04-481332 BWP M-3114L Euclid E-9671 Leland L-3101	Meritor 2210C7595 Midland CS40186 Spicer 18-529
		13-7/32"	-	-	Camshaft Kits		
					B8707 B8771 B8745 (Mack)	Batco 04-481331 BWP M-3114R Euclid E-9672 Leland L-3100	Meritor 2210B7594 Midland CS40187 Spicer 18-528
C594R		REPLACED BY C594R			B8745 (Mack)		
C733L		REPLACED BY C733AL			"Q"	Batco 04-461352 BWP M-2598L Euclid E-4733 Leland L-2889	Meritor 2210N5396 Midland Spicer 18-823
		13-7/16"	-	-	Camshaft Kits		
					B8707 B8771	Batco 04-461351 BWP M-2598R Euclid E-4732 Leland L-2888	Meritor 2210M5395 Midland Spicer 18-822
C732R		REPLACED BY C732AR			B8745 (Mack)		
C733AL		REPLACED BY C732AR			"Q-Plus"	Batco 04-481352 BWP M-2598L Euclid E-4733A Leland L-3105	Meritor 2210L7838 Midland CS40188 Spicer
		13-7/16"	-	-	Camshaft Kits		
					B8707 B8771	Batco 04-481351 BWP M-2598R Euclid E-4732A Leland L-3104	Meritor 2210K7837 Midland CS40189 Spicer
C732AR		REPLACED BY C732AR			B8745 (Mack)		