


# BRAKE CAMSHAFTS - TRAILER

Meritor 4000 - 6000



LH	RH	A	B	C	NOTES	REPLACES	
<b>C447L</b>		REPLACED BY C447AL			10 - Spline "Q"  Double-Grooved  Camshaft Kits	Batco 04-881732 BWP M-993L Euclid E-2447 Leland L-1652	Meritor 2210S4179 Midland Spicer 17-641
		17-5/16"	2-5/64"	1-25/32"		Batco 04-881731 BWP M-993R Euclid E-2448 Leland L-1651	Meritor 2210R4178 Midland Spicer 17-640
<b>C447AL</b>		17-5/16"	2-5/64"	1-25/32"	10 - Spline "Q-Plus"  Double-Grooved  Camshaft Kits	Batco BWP Euclid E-2447A Leland	Meritor R607066 Midland Spicer
	<b>C448R</b>					REPLACED BY C448AR	
<b>C441L</b>		REPLACED BY C441BL			28 - Spline "Q"  Double-Grooved  Camshaft Kits	Batco 04-891732 BWP M-990L Euclid E-2441A Leland L-1299	Meritor 2210M4329 Midland Spicer 17-627
		17-5/16"	2-5/64"	1-25/32"		Batco 04-891731 BWP M-990R Euclid E-2442A Leland L-1298	Meritor 2210L4328 Midland Spicer 17-626
<b>C441BL</b>		17-5/16"	2-5/64"	1-25/32"	28 - Spline "Q-Plus"  Double-Grooved  Camshaft Kits	Batco 04-931732 BWP M-3170L Euclid E-2441B/E-5506 Leland L-3113	Meritor 2210C6867 2210R8156 Midland CS41110 Spicer 17-721
	<b>C442R</b>					REPLACED BY C442BR	
<b>C449L</b>		REPLACED BY C449AL			10 - Spline "Q"  Double-Grooved  Camshaft Kits	Batco 04-882042 BWP M-994L Euclid E-2449 Leland L-1656	Meritor 2210W4183 Midland Spicer 17-633
		20-13/32"	2-5/64"	1-25/32"		Batco 04-882041 BWP M-994R Euclid E-2450 Leland L-1655	Meritor 2210V4182 Midland Spicer 17-632
<b>C449AL</b>		20-13/32"	2-5/64"	1-25/32"	10 - Spline "Q-Plus"  Double-Grooved  Camshaft Kits	Batco BWP Euclid E-2449A Leland	Meritor R607070 Midland Spicer
	<b>C450R</b>					REPLACED BY C450AR	